

AC DIGITAL CLAMP-ON MULTIMETER

True RMS 1,000A

Features:

- ➔ Include Power, Current Insulation Resistance & Temperature
- ➔ Min/Max & Data Hold
- ➔ Auto Off & Disable
- ➔ True Power, Apparent Power and Reactive Power, plus Horsepower, Power Factor, and Phase Angle with Lead/Lag Indicator
- ➔ Complete with Test Leads, Type K Probe -58° to 482° F / -50° C to 250° C, Case & 9V Battery

Ranges:

- AC/DC Voltage: 600 V
- AC Current: 1,000 A
- Resistance (Ω): 100 M
- Capacitance: 7,000 μF
- Frequency: 1 kHz
- Temperature: -58° to 1,000° F
- 50 C to 900 C
- CAT III-600V
- CE/UL Listed



Dimensions:
9" x 3" x 1.6"
(228 x 76 x 39 mm)

AC Digital Clamp-On Multimeter **Catalog Number** VAOT380976
Net Weight 16.4 oz. (465g), Shipping Weight 4 Lbs.

AC/DC DIGITAL CLAMP-ON MULTIMETER

True RMS 2,000A



Dimensions:
10" x 2.9" x 1.5"
(255 x 73 x 38 mm)

Features:

- ➔ Full Range Multimeter Functions with High Resolution to 0.1 μA/0.1mV
- ➔ Data Hold & Push Button Zero Adjust Improves DC Accuracy
- ➔ AC/DC Current Via Clamp with 0.1A Resolution
- ➔ Complete with Test Leads, Built-In Stand & 9V Battery

Ranges:

- AC/DC Voltage: 1,000 V
- AC/DC Current: 2,000 A
- Resistance (Ω): 40 M
- Capacitance: 50 μF
- Frequency: 100 kHz
- CAT III-1,000V
- CE/UL Listed

AC/DC Digital Clamp-On Multimeter **Catalog Number** VAOT380926
Net Weight 14 oz. (465g), Shipping Weight 3 Lbs.



MARTINDALE • PO Box 430 • Cleveland, OH 44107
Phone (216) 521-8567 • Fax Local 521-9476 / USA & Canada (800) 344-9191
E-Mail: sales@martindaleco.com
Web Site: www.martindaleco.com